

MORONG WATER DISTRICT

Morong, Rizal

WORK ORDER

W.O. No : 911

Date : October 28, 2021

Capital Expenditure

Project No.

Account No.

TO: CASTANEDA WELL DRILLING AND SUBMERSIBLE PUMP SERVICES

PR#: 21-09-285

Description of Work:

Check-up, repair and replacement of defective parts of Grundfos Submersible pump

* 2 unit SP60-10

* 1 unit SP30-13

Location of Work:

Starting Date:

Scheduled Completion:

Date Completed:

Final Completion:

Project Classification:

() Construction/Expansion of Major water works

() Installation of Machinery and equipment

() Major repairs or Replacements

() General Improvements

() Retirement of Fixed Assets

() Others (specify)

WORK BREAKDOWN

m. of inch Main

m. of inch Main

m. of inch Main

Service Laterals

Fire Hydrants

Sketch of Work to be done:

PROJECT COST

Particulars

Amount

Materials

P

Labor/Contract Cost

57,000.00

Overhead:

Supervision

Construction

Equipment charges

Transportation

Temporary Structures

Engineering

General Administration

Interest

Others

Total Overhead

TOTAL PROJECT COST:

P

57,000.00

Manner of Undertaking the Project:

() By Administration

() By Contractor

() Joint

Action Taken by General Manager:

() Approved

() Disapproved

() Deffered Until

Prepared by:

EUGENE R. IGNACIO

Purchaser

Checked Against Budget by:

JENNIFER T. SANTOS

DM, Finance Division

Approved:

DICKSON A. SAN JUAN, LPT,

MPA, MAEd

General Manager